



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

**Small Airplane Directorate  
Atlanta Manufacturing Inspection  
District Office  
1701 Columbia Avenue  
College Park, GA 30337**

October 26, 2009

PMA No. PQ1682CE

ADpma  
401 Century Ct  
Piney Flats, TN. 37686

**FEDERAL AVIATION ADMINISTRATION-PARTS MANUFACTURER APPROVAL**

Per 14 CFR part 21, Subpart K, we found design data submitted with your letters dated June 7, 2009, to meet the airworthiness requirements of the regulations for the products on which the parts are to be installed. We based our finding on identity. Also, we determined that your company set up the fabrication inspection system at, 401 Century Court, Piney Flats, Tennessee as required by 14 CFR, § 21.303(h). Therefore, we grant parts manufacturer approval (PMA), which authorizes you to produce the replacement parts in the enclosed Supplement No. 59.

We remind you that the provisions of 14 CFR, noted in our PMA letter of approval dated January 8, 2002, also apply to the enclosed PMA Listing-Supplement No. 59. Please keep the enclosed supplement with the original PMA letter as evidence of approval to produce the parts concerned.

Sincerely,

Jim Reeves  
Manager, Atlanta Manufacturing  
Inspection District Office

**FEDERAL AVIATION ADMINISTRATION-PARTS MANUFACTURER APPROVAL**

ADpma, LLC  
 401 Century Ct.  
 Piney Flats, TN 37686


PMA NO. PQ1682CE  
 SUPPLEMENT NO. 59  
 DATE: October 26, 2009


<u>Part Name</u>	<u>Part Number</u>	<u>Approved Replacement For Part Number</u>	<u>Approved Basis and Approved Design Data</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Washer, Locking Tab	ADP49174-1	Honeywell P/N 2714091-1	Test and Computations per 14 CFR § 21.303 <u>DWG NO:</u> ADP49174 <u>REV:</u> N/C <u>DATE:</u> 3/11/09 or later FAA Approved revisions	Bombardier       BAE Systems (Operations) Limited	CL-600-2B19 With Honeywell APU Model GTCP36-150[RJ] Installed.       BAe 146-100A, BAe 146-200A & BAe 146-300A With Honeywell APU GTCP36-100[M] Installed.       BAe 146-200A, Avro 146-RJ70A, Avro 146-RJ85A & Avro 146-RJ100A With Honeywell APU GTCP36-150[M] Installed.

-----END OF LISTING-----

**NOTE:**

- 1) Provide minor design changes in a manner as determined by the ACO. Handle major design changes to drawings and specifications in the same manner as that for an original FAA-PMA.
- 2) The FAA approved the ICA for the above parts with their designs. If the TC holder's ICA applies to these replacement parts, provide a statement noting such. If not, provide supplementary ICA per 14 CFR § 21.50. Make referral statements or supplemental ICA readily available per 14 CFR § 21.50.

  
 for Melvin D. Taylor  
 Manager, Atlanta Aircraft  
 Certification Office

  
 Jim Reeves  
 Manager, Atlanta Manufacturing  
 Inspection District Office